



By appointment to  
Her Majesty The Queen  
Building Façade Restoration  
and Conservation



## National Gallery

Working in the North wing of the National Gallery, among some of the finest religious paintings of the 14th and 15th centuries involved us in the supply and installation of a traditionally constructed Portland Stone cantilevered staircase to the North Stair, plinths and friezes in Ancaster Weatherbed and solid stone architraves in Westmoreland Kirkstone slate framing the entrances to each gallery.

Working with Purcell Miller Tritton Architects, in addition to the new stone, the pure Belgium Black flooring was restored to its original condition using traditional methods.

- Cleaning
- Repair
- Conservation
- Extension
- Adaption
- Surveys
- Budgets
- Technical advice



# PAYE

[www.payestone.co.uk](http://www.payestone.co.uk)

Stationmasters House Mottingham Station Approach London SE9 4EL  
Telephone 020 8857 9111 Fax 020 8857 9222  
[enquiries@payestone.co.uk](mailto:enquiries@payestone.co.uk)